




BT DP549 situated in New Office



Note : BT is responsible up to and including the master sockets on landlines, and up to the router, beyond that the DFR is responsible.

Norchard - MOP Circuits		
DFR bt007b		
ISSUE B	27/01/2018	Slave socket added to 845911 on page 2
ISSUE A	27/09/2015	Opening issue

BT DP549 situated in New Office

