



**Lydney Junction Signal Box
Low Volts Alarm & Clocks**

DFR ex038e

ISSUE E	23/10/2018	Clock outputs increased, Advance and stop provided
ISSUE D	16/4/2015	Errors at LV2 corrected
ISSUE C	28/09/2014	FA & PA relays removed, other wiring changes
ISSUE A	14/05/2014	Opening Issue

Dean Forest Railway

