



Norchard - Auto-Auto Relay Set with Regen DFR ex120d		
ISSUE D	10/09/2019	CD5 added to cover dis when BY1&2 changeover
ISSUE C	09/09/2019	CD5 added to cover dis when BY1&2 changeover
ISSUE B	07/06/2019	Circuit unchanged but resistor and relay coil values altered
ISSUE A	08/04/2019	Opening Issue