



- Notes :
- This relay set has been modified from an ATW56160 relay set.
 - It now has a battery testing facility for UAX13 use.
 - The D relay and rectifiers have been short circuited to prevent any attempt to meter.
 - The positive battery supply has been replaced with an internal earth.
 - Relay RT and the routine test facility has been removed.
 - Relay JG disconnected to ensure junction is not polarity conscious.
 - There will be no release alarm battery connected to U22.

Norchard - Auto-Auto RS with Regen		
DFR ex113a		
ISSUE A	21/08/2018	Opening Issue
Dean Forest Railway		

